

ACCIDENT CLASSIFICATION

UNIT	37 S.F.T.S. Calgary	COM.	4	PLACE	M.A.	DATE	27.6.43	TIME	1530
A/C TYPE	Harvard II Harvard IIB	No.	AJ.962 D FE.808	CRASH CAT.	C.2 D	H.Q. FILE	1300-AJ.962		
		S.E.		M.E.		DAY	X	NIGHT	X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Lynn, Frederick	CPL	539572	PP	Nil	No.	DATE
					A89	28.6
					D 14 (REVISED)	
					No.	CHECKED
					13	<input checked="" type="checkbox"/>
					#137	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp	A4340/8481 Nil						
Wasp	42-1125/21049 Nil	25	5	24	40	57	93

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

4

2

1

7

4

2

1

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STAT'RY

FATAL

INJ.

INJURY

3RD

5

RAF

M N

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PURPOSE OF FLIGHT:

Taxiing.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pilot of AJ962 misjudged distance
and struck the propellor of FE808
with his stbd wingtip.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~ 9

COLLISIONS.

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

XXX Log book endorsed "Gross CARELESSNESS"