

TYPE OF A/C		UNIT 128 Squadron Torbay		COM. RAC	PLACE M.A.	DATE 24.6.43	TIME 1045Z	COMMAND																							
		A/C TYPE Hurricane XII Hurricane XII		NO. 5490 5493	CRASH CAT. C.1 C.1	H.Q. FILE																									
TYPE OF UNIT	CATEGORY	PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL	MONTH																						
		Mil						No.		DATE																					
		NOT A FLYING ACCIDENT						D 14 (REVISED)																							
		Mil						No. 01/6		CHECKED X																					
D	C	ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT																					
		Packard Merlin A3591/AC-11/47718		Mil		INST.	NIGHT	ON TYPE			TOTAL																				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	RAF	M

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
1
FORCED LANDING
LAXING
LANDING
TAKE-OFF
FLIGHT
STAT BY
FATAL
INJ
INJURY
3RD
S
N

PURPOSE OF FLIGHT:

N.A.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

Hurricanes 5490 & 5493 were parked side by side on tarmac. Digby 750 was taxiing to parking space & upon turning, the slipstream of the Digby plus a very strong wind, caught the rudder of 5490, causing a/c to swerve on its tailwheel into the wing of 5493, damaging the aileron of 5493 & the rudder & fin of 5490.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

57. Miscellaneous

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil