

CATEGORY		TYPE OF UNIT		TYPE OF A/C		ACCIDENT CLASSIFICATION																STAGE OF FLIGHT		MONTH		COMMAND	
						UNIT 9 B.G.S. Mont Joli		COM. 3		PLACE Luceville, P.Q., 6 miles west M.A.				DATE 8.6.43		TIME 2100											
						A/C TYPE Battle I				Serial 7424				CRASH CAT. B		S.E. X		M.E.		DAY X		NIGHT					
						PERSONNEL				RANK		NUMBER		DUTY		INJURIES		SIGNAL									
						Kennison, J.D.				Sgt		R141657		P		Nil		NO.		DATE							
						Jerner, J.W.				LAC		R104201		AG		Nil		N.43		9.6							
						Roth, K.H.				LAC		R191716		AG		Nil		D 14 (REVISED)									
																		NO.		1		CHECKED					
										</																	

PURPOSE OF FLIGHT:

Scheduled camera gun exercise.

TECHNICAL OFFICER'S REPORT:

Suspected external glycol leak on "B" bank of engine.

NATURE OF ACCIDENT:

Engine failed, pilot carried out a forced landing with wheels retracted. When A/C came in contact with ground it hit a fence. Cockpit filled with fumes and smoke blinding pilot and making forced landing imperative.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

10/AUG/ES/04/11/00A/B.

CLASSIFICATION:

~~54. Engine failure in the air.~~

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

~~34. Wheels up landing.~~

~~41. Hitting obstructions.~~

26. Engine trouble -
Accidents

ACTION TAKEN:

NIL.