

CASPIR Aircraft Accident Cards

Serial: 11471

Title: Avro Anson Mk. II serial:11471 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-June-16. Anson II s/n 11471. This accident involved 2 people. Cameron MH, Howat JDW

Keywords: RCAFAnson II,11471,19 SFTS,19 Service Flying Training School,Aerodrome,1943-June-16,Cameron,HowatRCAF L20

Created: 1943-06-16

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11471>

ACCIDENT CLASSIFICATION

UNIT 19 S.F.T.S. Vulcan		COM 4	PLACE M.A.		DATE 16.6.43	TIME 1945			
A/C TYPE Anson II		No. 11471		CRASH CAT. C.5	H.Q. FILE 1100-114-71				
					S.E. X	M.E. X	DAY NIGHT		
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Howat, J.D.W.			PO	J21273	FI	Nil		NO.	DATE
Cameron, M.H.			AC2	R118008	Crewman	Slightly		M.103	16.6
								D 14 (REVISED)	
								NO.	CHECKED
								1	<input checked="" type="checkbox"/>
								#30	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs 26453/14939 Nil.				INST.	NIGHT	ON TYPE		TOTAL	
Jacobs 11697/14726 Nil.						SOLO	DUAL	SOLO	DUAL
				40	63	376	91	525	157

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJURY
3RD
5
RAF
M N

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

Night flying test.

TECHNICAL OFFICER'S REPORT:

Nil.

700/2009

NATURE OF ACCIDENT:

A/C being started, stbd engine running, U/C collapsed. Crewman disengaging battery cart was knocked down but was able to crawl from under A/C.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

24. Carelessness.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.