

CASPIR Aircraft Accident Cards

Serial: 1513

Title: Airspeed Oxford Mk. II serial:1513 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-12. Oxford II s/n 1513. This accident involved 2 people. Brown PW, Fletcher C

Keywords: RAF Oxford II, 1513, 35 SFTS, 35 Service Flying Training School, Aerodrome, 1943-June-12, Brown, Fletcher RCAF L20

Created: 1943-06-12

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#1513>

PURPOSE OF FLIGHT:

Day flying training.

TECHNICAL OFFICER'S REPORT:

Nil. TUC/PCDUW/UCOR⁴

NATURE OF ACCIDENT:

After landing pupil taxied to end of runway and proceeded to carry out cockpit drill but by mistake selected U/C lever. A/C was still in motion and stbd wheel retracted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~24. Carelessness.~~ 11

OTHERS.

SECONDARY OR CONTRIBUTORY FACTORS:

~~6. U/c drill at end of landing run~~

ACTION TAKEN:

Nil.

U/C DRILL - 33
ON GROUND.