

ACCIDENT CLASSIFICATION

UNIT	35 S.F.T.S. No. Battleford	COM.	4	PLACE	M.A.	DATE	14.6.43	TIME	1820
A/C TYPE	Oxford II	No.	V.3439	CRASH CAT.	C.10	H.Q. FILE	1300-V.3439		
S.E.		M.E.	X	DAY	X	NIGHT			

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL												
Fogelman, L.H.	LAC	1586254	PP	Nil	<table border="1"> <tr> <td>NO.</td> <td>DATE</td> </tr> <tr> <td>A676</td> <td>15.6</td> </tr> <tr> <td colspan="2">D 14 (REVISED)</td> </tr> <tr> <td>NO.</td> <td>CHECKED</td> </tr> <tr> <td>4</td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td colspan="2">#12</td> </tr> </table>	NO.	DATE	A676	15.6	D 14 (REVISED)		NO.	CHECKED	4	<input checked="" type="checkbox"/>	#12	
NO.	DATE																
A676	15.6																
D 14 (REVISED)																	
NO.	CHECKED																
4	<input checked="" type="checkbox"/>																
#12																	

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Che-tah X	178673/159567	Slightly		SOLO	DUAL	SOLO	DUAL
		12	5	9	23	33	74

ACCIDENT CLASSIFICATION

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STAIRY  
FATAL  
INJ.  
INJURY  
3RD  
5  
RAE  
M 2

PURPOSE OF FLIGHT:

Flying training.

TECHNICAL OFFICER'S REPORT:

Nil.

*05/13/1944*

NATURE OF ACCIDENT:

Port engine failed on take-off and A/C started swinging to left. Pupil throttle back but was unable to bring A/C to rest and it over-shot runway and in turning to avoid trees the stbd oleo leg gave way.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

14. Misuse of controls.

SECONDARY OR CONTRIBUTORY FACTORS:

25. Inexperience.

13. Engine failure

ACTION TAKEN:

Nil.