	0 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		A	CCIDE		CLAS	SIFICATIO			36/35/34/	32/32/2
A/C	Kingston, O	h	house, Gananoque & Kingston.						1300-FE297-1		
YPE OF /	A/C TYPE Harvard IIB			10. FIJ 2		CRASH			M.E. DAY	NIGHT	COMMAN
-	PERSO		RANK	NUMB	ER	DUTY	חראו	RIES	SIG	NAL	
Ц	Piercy, F.A		P/0	4149	2	FI	Fatal		NO.	DATE	1//
	Hicks, G.F.		ALA	FAA/F	<u> </u>	62 PF	Fa tal		C153	9-7	
	-								D 14 (r	REVISED)	S O
OF UNIT									NO.	CHENKED	FCED LIM
TYPE									#35		S TAXY!
	ENGINE ENGINE NUMBER (S) HOURS FLOWN BY PILOTS							STAGE OF			
Н					INST.	NIG	HT	N TYPE	ТО	TOTAL	
ORY							SOLO	DUAL	SOLO	DUAL	- V & / -
ATEGORY	-										LIGHT STATE
5			Α.(CIDEN	1 T C						1
	2/3/2/5/6	/1/0/0/0	757.	1/3/1	7	6/1	IFICATIO		. 7. 7. 7.	7. 7	(2)
	77777		$\frac{1}{1}$	~~ ?	7 7	ŸŸ	/.\/\?\/ _{\?} \	/ 2 ² / 2 ³	2/2 th /2 ^{to} /2 ^t	\v^\\v\	23/30 RKY

()))))))))))))))))))))))))))))))))))))	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,)))))))))
	TECHNICAL OFFICER'S REPORT:)
PURPOSE OF FLIGHT:)
, Seq. 13,14,15,17,22.	Nil		`
NATURE OF ACCIDENT: Aircraft were apparently carrying out dog-fighting when one A/C made a turn steeply to the left and close to the ground, causing its left wing to strike the ground and causing total destruction of the aircraft and killing its occupants. A/C were not in low flying area and were flying below lowest altitude authorized by S.S.O.	COURT OF INQUIRY OR INVESTIGATION FINDINGS: Pilot was flying too low as (Flying) and allowed his was ground. CONCLUSIONS OF A.I.B. Agree. Accident due to una	SUMMARY No. 1042 nd contrary to S.S.O. ing tip to touch the)
CLASSIFICATION:	·		,
16. Unauthorized low flying or	\sim)		į
aerobatics.)		,
20. Flew ento Ground.		•	
SECONDARY OR CONTRIBUTORY FACTORS:			
) 17. Disobodience of standing orders.	ACTION TAKEN:		
) 42. Mauthoused Law Supers P. C. A. F. L 20 (REVISED) 7M.4.43 (3202) K. P. 5051 H. Q. 885-L 20	Inquifficient evidence to c	convict, but evidence on that F/O Heath was pilo-	t
		, , , , , , , , , , ,	_