

CASPIR Aircraft Accident Cards

Serial: 2737

Title: North American Harvard Mk.II serial:2737 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-09. Harvard II s/n 2737. This accident involved 1 person. Bunday JG

Keywords: RAFHarvard II,2737,34 SFTS,34 Service Flying Training School,Halsom ELG,1943-July-09,BundayRCAF L20

Created: 1943-07-09

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2737>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE Helson F.I.G.	DATE 9-7-43	TIME 1515
A/C TYPE Harvard II	NO. 2737	CRASH CAT. C.7	H.Q. FILE 1100-27-37	
			S.E. X	M.E. X
			DAY X	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Runday, J.G.	LAC	1301397	PP	MI1	NO. A.632	DATE 10-7
					D 14 (REVISED)	
					NO. 7/11	CHECKED <input checked="" type="checkbox"/>
					39	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp	8430/4289 Nil			6	19	38	62

ACCIDENT CLASSIFICATION


COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY
3RD
S
RAF
M

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Local Exercises at R.1 Aerodrome

NATURE OF ACCIDENT:

Pupil made a crosswind landing and ground looped on landing run.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.



CLASSIFICATION:

~~38. Ground Loop~~

2. Stalling

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

25. Inexperience

ACTION TAKEN:

Log Book endorsed "Inexperience"