

## CASPIR Aircraft Accident Cards

---

**Serial:** FE338

**Title:** North American Harvard Mk. IIB serial:FE338 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-July-24. Harvard II s/n FE338. This accident involved 1 person. Hughes L

**Keywords:** RAFHarvard II,FE338,41 SFTS,41 Service Flying Training School,Ralph,1943-July-24,HughesRCAF L20

**Created:** 1943-07-24

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE338>



PURPOSE OF FLIGHT:

) Forced landing procedure.

TECHNICAL OFFICER'S REPORT:

No technical failure involved.

LUC/PCDUF/UCDL ✓

NATURE OF ACCIDENT:

) Pilot came in on approach while practicing forced landing procedure with flaps and wheels up. When he reached safety height (200 Ft.) he opened throttle but states he seemed to be caught in downrush of air and made wheels up landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

) ~~34. Wheels up landing.~~

) *J. Otter*

7

SECONDARY OR CONTRIBUTORY FACTORS:

) ~~32. Pilot error.~~

) ~~24. Carelessness.~~

ACTION TAKEN: