



PURPOSE OF FLIGHT:

Formation flying.

TECHNICAL OFFICER'S REPORT:

Short circuit in electrical wiring system.

NATURE OF ACCIDENT:

Pilot observed glow under instrument panel of A/C accompanied by dense smoke and fumes. He forced landed in field near main highway one mile east of Chicoutimi, Que.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*150 F. 16 / I / 12 ✓*

CLASSIFICATION:

~~27. Fire in the air .~~

*17. Forced Landing 18*

SECONDARY OR CONTRIBUTORY FACTORS:

~~33. Technical Defect~~

*85*

ACTION TAKEN:

NIL