

CASPIR Aircraft Accident Cards

Serial: AJ964

Title: North American Harvard Mk. II serial:AJ964 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-27. Harvard II s/n AJ964. This accident involved 2 people. Bullough RO, Wathieu JDF

Keywords: RAFHarvard II,AJ964,34 SFTS,34 Service Flying Training School,Aerodrome,1943-July-27,Bullough,WathieuRCAF L20

Created: 1943-07-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ964>

ACCIDENT CLASSIFICATION												
UNIT No. 34 S.F.T.S.		COM. # 4		PLACE N.A.				DATE 27-7-43		TIME 0900		
Medicine Hat, Alta.								H.Q. FILE				
A/C TYPE Harvard II				NO. AJ964		CRASH CAT. D 1/18		S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL				
Bullough, R.O.			SGT	1078774	PT	Nil		NO.	DATE			
Wathieu, J.D.F.			LAC	1424942	PP	Nil		D 14 (REVISED)				
								NO. 34	CHECKED <input checked="" type="checkbox"/>			
								No. 125				
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS							
Wasp S3H1		9979/A213343 Nil			INST.	NIGHT	ON TYPE		TOTAL			
						SOLO	DUAL	SOLO	DUAL			
						300	70	379	125			
ACCIDENT CLASSIFICATION												

Accident

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

COMMAND
 MONTH
 STAGE OF FLIGHT
 FORCED LANDING
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ
 INJURY
 3RD
 5
 N

PURPOSE OF FLIGHT:

Dual exercises.

TECHNICAL OFFICER'S REPORT:

Tail wheel tyre burst after life of 125 hrs. 30 mins

NATURE OF ACCIDENT:

Tail wheel tyre burst on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

202/150

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL