

ACCIDENT CLASSIFICATION									
UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE M.A.			DATE 28-7-43		TIME 1200	
A/C TYPE Harvard IIB			NO. FE825		CRASH CAT. D. 27	S.E. X	M.E. 	DAY X	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Frogner, J.H.		Pte	1780	PP	Nil		NO.	DATE	
<i>Incident</i>						D 14 (REVISED)			
						NO.	CHECKED		
						38	4		
						#133			
ENGINE		ENGINE NUMBER(S)		HOURS FLOWN BY PILOTS					
Wasp		42-1145/21069 Nil		INST.	NIGHT	ON TYPE		TOTAL	
				-	-	SOLO	DUAL	SOLO	DUAL
						42	52	72	97
ACCIDENT CLASSIFICATION									

PURPOSE OF FLIGHT:

Solo exercises.

NATURE OF ACCIDENT:

Port engine nacelle panel came off in flight.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

IM/AMS

CLASSIFICATION:

28. Structural failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil