

CASPIR Aircraft Accident Cards

Serial: BW279

Title: Harvard II serial:BW279 - Crash Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-29. Harvard II s/n BW279. This accident involved 1 person. Hoyne JA

Keywords: RAFHarvard II,BW279,41 SFTS,41 Service Flying Training School,Aerodrome,1943-July-29,HoyneRCAF L20

Created: 1943-07-29

TYPE OF A/C		UNIT No. 41 S.F.T.S.		COM.	PLACE		DATE	TIME	COMMAND			
		Weyburn, Sask.		# 2	M.A.		29-7-43	1850				
TYPE OF UNIT		A/C TYPE		NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT	MONTH		
		Harvard II										BW279
CATEGORY		PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		STAGE OF FLIGHT	
		Hoyne, J.A.		LAC	1623330	PP	Nil		NO.	DATE		
TYPE OF FLIGHT										FORCED LANDING		
											TAXYING	
TYPE OF FLIGHT										LANDING		
											TAKE-OFF	
TYPE OF FLIGHT										FLIGHT		
											STATRY	
TYPE OF FLIGHT										FATAL		
											INJ	
TYPE OF FLIGHT										INJURY		
											SHD	
TYPE OF FLIGHT										RAF		
											M N	
TYPE OF FLIGHT										181		

ACCIDENT CLASSIFICATION

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Exercises Nos.9,10,13,15,17,22.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

On landing A/C swung to left. Pilot applied opposite rudder but failed to correct swing. Right wing touched ground, damaging wing tip, mainplane and aileron.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.



CLASSIFICATION:

~~38. Ground loop.~~

A. Swung. 2

SECONDARY OR CONTRIBUTORY FACTORS:

~~25. Inexperience.~~

~~61. Swinging on landing.~~

ACTION TAKEN:

Nil