

ACCIDENT CLASSIFICATION											
UNIT 34 O.T.U. Pennfield Ridge		COM. EAC		PLACE M.A.		DATE 3.7.43		TIME 0735 GMT		COMMAND	
A/C TYPE Ventura I		NO. 672		CRASH CAT. B		H.Q. FILE 1300-AE.672		S.E. X			
PERSONNEL		RANK		NUMBER		DUTY		INJURIES		SIGNAL	
Laws, R. (NZ)		SGT		421515		P		Nil		NO. A211	
Casey, G.P.J.		SGT		R164711		WAG		Nil		DATE 3.7	
										D 14 (REVISED)	
										NO. 1	
										CHECKED ☒	
										1	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS							
Wasp		P.A199381/1487 Nil		INST.		NIGHT		ON TYPE		TOTAL	
		S.A199380/1486 Slight		41		24		SOLO 4		DUAL 7	
								SOLO 105		DUAL 134	
ACCIDENT CLASSIFICATION											

PURPOSE OF FLIGHT:

Day training

TECHNICAL OFFICER'S REPORT:

Nil

10/75 ✓

NATURE OF ACCIDENT:

Undershot and U/C collapsed on rough ground short of runway.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~30. Undershooting~~

3

3. Undershot

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error~~

ACTION TAKEN:

Log book endorsed "Error of judgment".