

ACCIDENT CLASSIFICATION																
UNIT No. 145 Sqn., Torbay, Hfld.			COM. BAC		PLACE F.A.A.			DATE 20-7-43		TIME 2257						
A/C TYPE Ventura V					NO. 2168		CRASH CAT. B		S.E.	M.E. X	DAY	NIGHT X				
PERSONNEL					RANK	NUMBER	DUTY		INJURIES		SIGNAL					
Dalglish, J.P.					E/C	J10579	P		Nil		NO.	DATE				
Griff, M.E.					WO2	R99803	NAV		Nil							
Purdie, J.D.					E/C	R97309	WOAC		Nil			D 14 (REVISED)				
											NO.	CHECKED				
													No. 11			
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS											
P & V R2800		5543/7551 Nil			INST.		NIGHT		ON TYPE				TOTAL			
		5547/7051 Nil							SOLO		DUAL		SOLO		DUAL	
					82		39		59		17		426		273	
ACCIDENT CLASSIFICATION																

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

4

2

1

7

4

2

1

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATUTORY

FATAL

INJ

3RD

5

RAF

M

N

PURPOSE OF FLIGHT:

Night circuits and landings.

TECHNICAL OFFICER'S REPORT:

Tire blew, tearing at tread.

NATURE OF ACCIDENT:

Stbd. tire blew on landing. A/C left runway after landing, struck a pile of stone damaging the tail section, flaps and stbd. wheel.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LCC/UTR

CLASSIFICATION:

~~43. Tire trouble.~~

7. Others

7

SECONDARY OR CONTRIBUTORY FACTORS:

~~61. Swinging on landing.~~

~~41. Hitting obstructions.~~

37. Tire Burst.

3 7

ACTION TAKEN:

NIL