



PURPOSE OF FLIGHT:

) Dual Instruction

TECHNICAL OFFICER'S REPORT:

Nil

*Handwritten notes and signatures*

NATURE OF ACCIDENT:

) While taxiing on tarmac, 7597 swung  
) hitting 7532 which was parked with  
) engine shut down.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

) ~~3. Hitting other aircraft~~

) *9. Collision*

SECONDARY OR CONTRIBUTORY FACTORS:

) ~~24. Carelessness~~

ACTION TAKEN:

Instructor placed on charge. Log book endorsed.