



PURPOSE OF FLIGHT:

Routine training flights, service.

NATURE OF ACCIDENT:

A/c AR850 carrying out gliding approach struck a/c BS910 carrying out engine assisted approach on same runway. Very Light gun misfired thus no signal could be given.

TECHNICAL OFFICER'S REPORT:

No technical defect.

*MULT*  
*LCA/PCL*  
*LCA/PCL/XA*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~45. Collision~~  
*6. Collision*

*6*

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Log book endorsed