

## CASPIR Aircraft Accident Cards

---

**Serial:** X6961

**Title:** Airspeed Oxford Mk. I serial:X6961 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-July-16. Oxford II s/n X6961. This accident involved 1 person. Fletcher GK

**Keywords:** RAF Oxford II,X6961,35 SFTS,35 Service Flying Training School,Aerodrome,1943-July-16,Fletcher RCAF L20

**Created:** 1943-07-16

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#X6961>



PURPOSE OF FLIGHT:

Flying training

NATURE OF ACCIDENT:

Pupil held off high on coming in to land and right wing dropped. Overshoot action was attempted but too late to prevent stbd. wheel from hitting ground and breaking. A/C then ground looped.

CLASSIFICATION:

~~39. Flattening out too soon~~

*A. Heavy*

*A*

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error~~

~~25. Inexperience~~

~~38. Ground Loop~~

TECHNICAL OFFICER'S REPORT:

Nil

*LH/PSMH/USH*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil