

CASPIR Aircraft Accident Cards

Serial: AS920

Title: Airspeed Oxford Mk. II serial:AS920 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-24. Oxford II s/n AS920. This accident involved 1 person. Spencer JJ

Keywords: RAFOxford II,AS920,35 SFTS,35 Service Flying Training School,Aerodrome,1943-July-24,SpencerRCAF L20

Created: 1943-07-24

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS920>

ACCIDENT CLASSIFICATION

UNIT No.35 S.F.T.S. North Battleford.	COM. # 4	PLACE M.A.	DATE 24-7-43		TIME 0225	
			H.Q. FILE 1300-AS920			
A/C TYPE Oxford II	NO. AS920	CRASH CAT. C	S.E.	M.E. X	DAY	NIGHT X
PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Spencer, J.J.	CPL	920715	PP	Nil	NO. A851	DATE 24-7
					D 14 (REVISED)	
					NO. 8	CHECKED X
					#23	
ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS				
Cheetah	P147857/AS41168 Nil	INST.	NIGHT	ON TYPE		TOTAL
	S179087/AS21053 Nil			SOLO	DUAL	SOLO DUAL
		18	17	60	74	92 120

COMMAND

MONTH

STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- START-UP
- FATAL
- INJ.
- INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Night flying training.

TECHNICAL OFFICER'S REPORT:

Nil

LO/PSO/USG

NATURE OF ACCIDENT:

Pupil doing night circuits and landings overshoot the runway and hit a boundary marker causing damage to the a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~29. Overshooting runway.~~ 1

1. Overshot

SECONDARY OR CONTRIBUTORY FACTORS:

~~41. Hitting obstructions.~~

24. Wk strain

34

ACTION TAKEN:

Nil