

CASPIR Aircraft Accident Cards

Serial: FE351

Title: North American Harvard Mk. IIB serial:FE351 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-06. Harvard II s/n FE351. This accident involved 1 person. Byfield D

Keywords: RAFHarvard II,FE351,41 SFTS,41 Service Flying Training School,Aerodrome,1943-August-06,ByfieldRCAF L20

Created: 1943-08-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE351>


ACCIDENT CLASSIFICATION

| | | | | | | | | |
|-------------------------------------|----------------------|------------------|-----------------------|---------------|--------------------|------------------|---|------|
| UNIT 41 S.F.T.S. Weyburn | | COM. 2 | PLACE M.A. | | DATE 6-8-43 | TIME 1500 | | |
| A/C TYPE Harvard II | | NO. FE351 | CRASH CAT. C.7 | S.E. X | M.E. | DAY X | NIGHT | |
| PERSONNEL | | RANK | NUMBER | DUTY | INJURIES | | SIGNAL | |
| Byfield, D | | LAC | 1086788 | PP | Nil | | NO. A.143 DATE 7-8 | |
| | | | | | | | D 14 (REVISED) | |
| | | | | | | | NO. 5 CHECKED <input checked="" type="checkbox"/> | |
| | | | | | | | #18 | |
| ENGINE | ENGINE NUMBER (S) | | HOURS FLOWN BY PILOTS | | | | | |
| Wasp | 15771/42/635 Slight. | | INST. | NIGHT | ON TYPE | | TOTAL | |
| | | | | | SOLO | DUAL | SOLO | DUAL |
| | | | 8 | 5 | :15 | 6 | 33 | 44 |

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY



PURPOSE OF FLIGHT:

Exercises 7,8,9.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pilot made landing with drift, bounced and the port wing touched the ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LH/PSHL ✓

CLASSIFICATION:

~~40. Heavy landing flying into ground.~~

4 Heavy.

A

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Nil