

## CASPIR Aircraft Accident Cards

---

**Serial:** FE447

**Title:** North American Harvard Mk. IIB serial:FE447 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-August-08. Harvard IIB s/n FE447. This accident involved 2 people. Kraft E, Switch L

**Keywords:** RAFHarvard IIB,FE447,34 SFTS,34 Service Flying Training School,Aerodrome,1943-August-08,Kraft,SwitchRCAF L20

**Created:** 1943-08-08

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE447>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE Main Aerodrome			DATE 8-8-43	TIME 1015		
A/C TYPE Harvard IIB		NO. FE447		CRASH CAT. D 1		S.E. X	M.E.	DAY X	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Switon, L.		F/S	780519	FI	Nil		NO.	DATE	
Kraft, E.		LAC	788067	PP	Nil		D 14 (REVISED)		
<p><i>President</i></p>						NO.	CHECKED		
						8/7	<input checked="" type="checkbox"/>		
						37			
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp R1340-AN-1		15881/42-745 Nil		INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
						913	2	1373	37

ACCIDENT CLASSIFICATION

COMMAND MONTH STAGE OF FLIGHT

4  
1  
2  
7  
4  
2  
1  
2  
1  
1  
FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INI.  
INJURY  
3RD  
5  
RAF  
M  
K

PURPOSE OF FLIGHT:

Dual Exercises

TECHNICAL OFFICER'S REPORT:

Stbd. wheel fairing lost during aerobatics

NATURE OF ACCIDENT:

Fairing off starboard wheel found to be missing at completion of flight. Presumably lost in the air.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  
FINDINGS: SUMMARY No.

*IM/HMS*

CLASSIFICATION:

57. Miscellaneous

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

N.A.