

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:
) Seq. 10,15,16,17) NATURE OF ACCIDENT:	100/A00/PSF/8/N
Aircraft appears to have crashed in spin or spiral dive.	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY No. 10 94
CLASSIFICATION: 23. Spinning.	Whilst on an authorized flight and on Air Force duties met instataneous death when unable to regain control of a/c during a spin, crashed into the grou at a sufficiently steep angle without rebounding to completely demolish the a/c. Genclusions of A.I.B. Pupil pilot solo recovered from a voluntary spin at such a low altitude that a crash was inevitable. Inexperience and lack of instruction were contributory factors. Note: Spins had been demonstrated to pupil but 3
19. Out of boutsel 19	times while at S.F.T.S. and had not had any dual spins since 28-7-43.
) SECONDARY OR CONTRIBUTORY FACTORS: 25. Inexperience.	ACTION TAKEN:
R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L 20	C. C. LTD. 7084-43