

CASPIR Aircraft Accident Cards

Serial: AJ737

Title: North American Harvard Mk. II serial:AJ737 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-10. Harvard II s/n AJ737. This accident involved 1 person. Gray W

Keywords: RAFHarvard II,AJ737,34 SFTS,34 Service Flying Training School,Holsom R1 Aerodrome,1943-August-10,GrayRCAF L20

Created: 1943-08-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ737>

PURPOSE OF FLIGHT:

Precision landings.

NATURE OF ACCIDENT:

Pupil landed with u/c not locked down. U/c collapsed on landing.

TECHNICAL OFFICER'S REPORT:

Horn blew before pilot attempted to lower U/C but not after. U/C retracting mechanism O.K. with exception of one lead on horn circuit disconnected.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/UDW ✓

CLASSIFICATION:

~~91. Undercarriage down but not fully locked.~~

5. U/c failure

5-

SECONDARY OR CONTRIBUTORY FACTORS:

~~33. Technical Defect~~

33. U/c Defect.

35-

ACTION TAKEN: