

CASPIR Aircraft Accident Cards

Serial: 2759

Title: North American Harvard Mk.II serial:2759 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-11. Harvard II s/n 2759. This accident involved 1 person. Rhodes H

Keywords: RAFHarvard II,2759,41 SFTS,41 Service Flying Training School,Ralph Saskatchewan,1943-August-11,RhodesRCAF L20

Created: 1943-08-11

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2759>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Forced landing procedure.

Nos. 5 & 9 cylinder heads cracked.

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Pilot was climbing away after doing a forced landing practice when engine began to vibrate at 700' and finally stopped. Pilot made wheels down landing in wheat field with no damage to the airframe.

SFE/ES/MP/M/I

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil