

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat.	COM. 4	PLACE M.A.	DATE 11-8-43	TIME 0210
A/C TYPE Harvard II		NO. 2788	CRASH CAT. C1	H.Q. FILE 1100-27-88
			S.E. X	M.E. DAY
			NIGHT X	


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Vorssegaer, Van de Werve	LAC	1424895	PP	Nil	NO. A807	DATE 11-8
					D 14 (REVISED)	
					NO. 11	CHECKED
					#34	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
		INST.	NIGHT	ON TYPE		TOTAL		
				SOLO	DUAL	SOLO	DUAL	
Wasp	11542/A213813	Nil	24	11	23	47	58	93
								151

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
3RD  
INJURY



PURPOSE OF FLIGHT:

Night flying circuits.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

A/c swung on landing at night and ground looped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

15/1055 ✓

CLASSIFICATION:

~~61. Swinging on landing.~~

2. *Swung.*

2

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

ACTION TAKEN:

Log book endorsed.