

CASPIR Aircraft Accident Cards

Serial: FE937

Title: North American Harvard Mk. IIB serial:FE937 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-13. Harvard II s/n FE937. This accident involved 2 people. Goodman FE, Reade FM

Keywords: RAFHarvard II,FE937,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-August-13,Goodman,ReadeRCAF L20

Created: 1943-08-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE937>

PURPOSE OF FLIGHT:

Forced landing Practice

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil came in to land under direction
of instructor. Failed to lower u/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/PEDOF/UCDL ✓

CLASSIFICATION:

~~34. Wheels up landing.~~

7. Other

7

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

32. U/c Drill - In air

3 2

ACTION TAKEN:

Nil