

## CASPIR Aircraft Accident Cards

---

**Serial:** 2645

**Title:** North American Harvard Mk.II serial:2645 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-August-19. Harvard II s/n 2645. This accident involved 1 person. Van Hamme AYJ

**Keywords:** RAFHarvard II,2645,34 SFTS,34 Service Flying Training School,Aerodrome,1943-August-19, Van HammeRCAF L20

**Created:** 1943-08-19

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2645>


ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE MA.		DATE 19-8-43	TIME 1430			
A/C TYPE HARVARD II		NO. 2645	CRASH CAT. "D" <sup>1</sup> / <sub>2</sub>		S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Van Hamme, A.Y.J.		Lac	1424990	PP	Uninj.		NO. 31	DATE	
							D 14 (REVISED)		
							NO. 31	CHECKED <input checked="" type="checkbox"/>	
							#141		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp S3HI		Y260/5327 Ni1		INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				-	-	8	16	46	49

ACCIDENT CLASSIFICATION

CATEGORY  
TYPE OF UNIT  
TYPE OF A/C  
COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STATUTORY  
FATAL  
INJ.  
3rd  
5  
RAJ  
M



PURPOSE OF FLIGHT:

Solo exercise.

NATURE OF ACCIDENT:

A/C ground looped on landing.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

15/PSS

CLASSIFICATION:

38. Ground loop.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed.