

CASPIR Aircraft Accident Cards

Serial: AJ942

Title: North American Harvard Mk. II serial:AJ942 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-20. Harvard II s/n AJ942. This accident involved 2 people. Harris HJM, Wilkinson W

Keywords: RAFHarvard II,AJ942,34 SFTS,34 Service Flying Training School,Aerodrome,1943-August-20,Harris,WilkinsonRCAF L20

Created: 1943-08-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ942>

ACCIDENT CLASSIFICATION

UNIT No. 34 S.F.T.S.
Medicine Hat.

COM. # 4

PLACE M.A.

DATE 20-8-43

TIME 1600

H.Q. FILE

A/C TYPE Harvard II

No. AJ942

CRASH CAT. D 1/72

S.E. X

M.E.

DAY X

NIGHT

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Wilkinson, W.

F/O

124495

FI

Nil

Harris, H.J.M.

LAC

591919

PP

Nil

No.

DATE

D 14 (REVISED)

No.

36

CHECKED

X

No. 95

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Wasp S3H1

11561/213832

Nil

INST.

NIGHT

ON TYPE

TOTAL

-

-

SOLO 624

DUAL 121

SOLO 686

DUAL 136

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3rd
INJURY

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Dual instruction.

TECHNICAL OFFICER'S REPORT:

Tail wheel tyre burst after life of 92 hours.

NATURE OF ACCIDENT:

Tail wheel tyre burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TUC/UTWF

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL