

ACCIDENT CLASSIFICATION

UNIT No. 34 S.F.T.S. Medicine Hat.		COM. # 4	PLACE M.A.		DATE 22-8-43	TIME 0115		
A/C TYPE Harvard II		No. AJ753	CRASH CAT. D 1 1/2		S.E. X	M.E.	NIGHT X	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES			SIGNAL
Payn, F.V.		P/O	146312	FI	Nil			No. DATE
Crekillie, A.F.		LAC	1424981	PP	Nil			No. DATE
								D 14 (REVISED)
								No. CHECKED
								38 4
								No.92
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Wasp S3H1		4243/8384 Nil		INST.	NIGHT	ON TYPE		TOTAL
						SOLO	DUAL	SOLO DUAL
				62	160	1112	1	1320 86
				20	7	22	29	58 81

COMMAND MONTH STAGE OF FLIGHT

- FORCED LANDING
- FAXYING
- LANDING
- TAKE-OFF
- FLIGHT
- FATAL
- INI.
- INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

N.F. Circuits and Landings.

TECHNICAL OFFICER'S REPORT:

No technical failure.

NATURE OF ACCIDENT:

A/C was landing at night under very strong and variable wind conditions. A/C started to swing on landing, and instructor was unable to prevent wing tip striking ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

1.5/1/52/E/WWC

CLASSIFICATION:

35. Cross winds and gusts.

SECONDARY OR CONTRIBUTORY FACTORS:

61. Swinging on landing.

ACTION TAKEN:

NIL