

CASPIR Aircraft Accident Cards

Serial: AJ753

Title: North American Harvard Mk. II / 2A serial:AJ753 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-22. Harvard II s/n AJ753. This accident involved 2 people. Crekillie AF, Payn FV

Keywords: RAFHarvard II,AJ753,34 SFTS,34 Service Flying Training School,Aerodrome,1943-August-22,Crekillie,PaynRCAF L20

Created: 1943-08-22

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ753>

ACCIDENT CLASSIFICATION

UNIT No. 34 S.F.T.S. Medicine Hat.		COM. # 4	PLACE M.A.		DATE 22-8-43	TIME 0115			
A/C TYPE Harvard II		No. AJ753	CRASH CAT. D 1 1/2		S.E. X	M.E.	NIGHT X		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES			SIGNAL	
Payn, F.V.		P/O	146312	FI	Nil			No.	DATE
Crekillie, A.F.		LAC	1424981	PP	Nil			D 14 (REVISED)	
								No.	CHECKED
								38	X
								No.92	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp S3H1		4243/8384 Nil		INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				62	160	1112	1	1320	86
				20	7	22	29	58	81

COMMAND
 MONTH
 STAGE OF FLIGHT

FORCED LANDING
 FAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

N.F. Circuits and Landings.

TECHNICAL OFFICER'S REPORT:

No technical failure.

NATURE OF ACCIDENT:

A/C was landing at night under very strong and variable wind conditions. A/C started to swing on landing, and instructor was unable to prevent wing tip striking ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

1. 2/1/52/E/WWC

CLASSIFICATION:

35. Cross winds and gusts.

SECONDARY OR CONTRIBUTORY FACTORS:

61. Swinging on landing.

ACTION TAKEN:

NIL