


61 ( ) 60 ( ) 59 ( ) 58 ( ) 57 ( ) 56 ( ) 55 ( ) 54 ( ) 53 ( ) 52 ( ) 51 ( ) 50 ( ) 49 ( ) 48 ( ) 47 ( ) 46 ( ) 45 ( ) 44 ( ) 43 ( ) 42 ( ) 41 ( ) 40 ( ) 39 ( ) 38 ( ) 37 ( ) 36 ( ) 35 ( ) 34 ( ) 33 ( ) 32 ( ) 31 ( )

ACCIDENT CLASSIFICATION

UNIT No.1 Ref. Sqn. Rockeliffe, Ont.	COM. <u>3</u> <del>APPL</del>	PLACE Forced Landing Field, Navan, Ont.	DATE 3-8-43	TIME 1615
A/C TYPE Anson II		NO. 7162	CRASH CAT. C 5 <i>Engine only</i>	H.Q. FILE 1100-71-62
		S.E.	M.E.	DAY
			X	X
		NIGHT		

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Hanchet-Taylor, A.J.	W/C	C1775	PP	Nil	No. A449	DATE 4-8
					D 14 (REVISED)	
					No.	CHECKED

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	INST.	NIGHT	HOURS FLOWN BY PILOTS			
				ON TYPE		TOTAL	
Jacobs L6MB	25392/14081	Nil		SOLO	DUAL	SOLO	DUAL
	25391/14080	Nil					

FORCED LANDING ( )  
TAXIING ( )  
LANDING ( )  
TAKE-OFF ( )  
FLIGHT ( )  
STATIONARY ( )  
FATAL ( )  
INJ. ( )  
3RD ( )  
INJURY ( )  
5 ( )

ACCIDENT CLASSIFICATION

1 ( ) 2 ( ) 3 ( ) 4 ( ) 5 ( ) 6 ( ) 7 ( ) 8 ( ) 9 ( ) 10 ( ) 11 ( ) 12 ( ) 13 ( ) 14 ( ) 15 ( ) 16 ( ) 17 ( ) 18 ( ) 19 ( ) 20 ( ) 21 ( ) 22 ( ) 23 ( ) 24 ( ) 25 ( ) 26 ( ) 27 ( ) 28 ( ) 29 ( ) 30 ( ) 31 ( ) 32 ( ) 33 ( ) 34 ( ) 35 ( ) 36 ( ) 37 ( ) 38 ( ) 39 ( ) 40 ( ) 41 ( ) 42 ( ) 43 ( ) 44 ( ) 45 ( ) 46 ( ) 47 ( ) 48 ( ) 49 ( ) 50 ( ) 51 ( ) 52 ( ) 53 ( ) 54 ( ) 55 ( ) 56 ( ) 57 ( ) 58 ( ) 59 ( ) 60 ( ) 61 ( ) 62 ( )

PURPOSE OF FLIGHT:

Training flight.

TECHNICAL OFFICER'S REPORT:

Cylinder cracked and broke loose in flight.

NATURE OF ACCIDENT:

Cylinder of port engine blew out in the air.

*SFL/ET/MP/MF*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil