

CASPIR Aircraft Accident Cards

Serial: 11536

Title: Avro Anson Mk. II serial:11536 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1943-August-12. They are: Anson II s/n 11520, Anson II s/n 11536. This accident involved 2 people. Roy PE, Commings EJ This accident had 1 fatality. Sergeant Paul Edward Antoine Roy RCAF Killed in Flying Accident service no:R/185372 Anson 11520

Keywords: RCAFAnson II,11536,17 SFTS,17 Service Flying Training School,Hartney,1943-August-12,Commings,RoyRCAF L20

Created: 1943-08-12

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11536>

PURPOSE OF FLIGHT:

Formation flying practise with I.T.

NATURE OF ACCIDENT:

While forming leader instructed pupils to change formation from echelon stbd to line astern. LAC Hoy in No. 2 position and LAC Commins in No. 3 position both a/c dropped back and collided.

CLASSIFICATION:

~~26. Collision in the air.~~
21. Collision type 21

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error~~

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2019

Collision in mid air caused by pilot error of LAC Commins.

Conclusions of A.I.B.

The provisions of No. 2 T.C.T.I. were not complied with, re instruction in formation flying. See Summary No. 2019 for details.

ACTION TAKEN:

Nil