

62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 15 E.F.T.S. Egina	COM. 4	PLACE North of M.A.	DATE 29-8-43	TIME 1210
A/C TYPE CORNELL II	No. 14492	CRASH CAT. "D"	S.E. X	M.E. X
H.Q. FILE 1100-144-92		DAY X	NIGHT	

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Marshall, E.D.	Lac	R163016	PP	Uninj.	NO. DATE
					D 14 (REVISED)
					NO. CHECK'D
					22 A
					#68

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Ranger	37126/6642 Nil	8	5	SOLO	DUAL	SOLO	DUAL
				39	35	39	35

FORCED LANDING
TAXYING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
5
4

ACCIDENT CLASSIFICATION


1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31

TYPE OF A/C

TYPE OF UNIT

CATEGORY

✓



PURPOSE OF FLIGHT:

Seq. 17,22,25.

TECHNICAL OFFICER'S REPORT:

Nil

100/100 J/pok

NATURE OF ACCIDENT:

While practising a forced landing out-
side forced landing field came below
50' and struck some trees.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

24. Carelessness

SECONDARY OR CONTRIBUTORY FACTORS:

- 16. Unauthorized low flying
- 57. Miscellaneous

ACTION TAKEN:

Awarded 14 days detention and to discontinue all
air-crew training.