

ACCIDENT CLASSIFICATION										
UNIT 11 E.F.T.S.		COM. 3	PLACE 4 miles N.W. of M.A.			DATE 31-8-43	TIME 1445		H.Q. FILE 1100-45-77	
A/C TYPE FINCH II			NO. 4577	CRASH CAT. "A"		S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL			
Smith, A.L.		P/O	J24578	FI	Slightly Inj.		NO.	DATE		
Hyndman,		Lac	R516104	PP	Uninj.		D 14 (REVISED)			
							NO.	CHECKED		
							1	X		
							#38			
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT		
Kinner B-5		6353/1708		serious		ON TYPE		TOTAL		
				INST.	NIGHT	SOLO	DUAL	SOLO	DUAL	
				50	50	325	36	463	155	
				2	-	12	16	12	16	
ACCIDENT CLASSIFICATION										

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
3RD  
5

RAF

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual Instructions.

Nil

NATURE OF ACCIDENT:

*1 LFM / 7100 / PCPE / 1 2 / PM / 10/12*

Practicing forced landings, experienced engine failure causing a/c to strike bushes.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure.~~ 17  
17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - Accident  
26

ACTION TAKEN:

Log book endorsed "Carelessness" and pilot logged.