

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Bagotville		COM. IAC	PLACE H.A.		DATE 10-8-43	TIME 1630 GBT				
A/C TYPE Hurricane X11A Hurricane X11A		No. EW856 EW859	CRASH CAT. 0.2 0.3		S.E. X X	M.E.	DAY X X	NIGHT		
PERSONNEL			RANK	NUMBER	DUTY	INJURIES			SIGNAL	
Scott, A.D.			SGT	WZ24954	2	Nil			No.	DATE
									A.100	10-8
									D 14 (REVISED)	
									No.	CHECKED
									2	<input checked="" type="checkbox"/>
									3	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT		
Merlin		AG41-47767/AC2740 P12 A.301 Nil		INST.	NIGHT	ON TYPE		TOTAL		
						SOLO	DUAL	SOLO	DUAL	
				39	24	9	-	115	108	

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3RD
5
M X

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M X

PURPOSE OF FLIGHT:

Local flying.

TECHNICAL OFFICER'S REPORT:

Nil

Handwritten notes:
1. 2/11/50
2. 1/11/50

NATURE OF ACCIDENT:

BW856 taxied into parked a/c BW859
damaging both wings and prop. of BW856
and port wing of BW859. Gusty wind
conditions at time of accident.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~35. Cross winds and gusts.~~

9. Collision

9

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

~~3. Hitting other aircraft~~

ACTION TAKEN:

Log book endorsed. Retarded one course.