

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 7 E.F.T.S. Windsor	COM. 1	PLACE I.A.	DATE 6-6-73	TIME 1700
A/C TYPE Tiger 10th		No. 3863-D 0000	CRASH CAT. C	H.Q. FILE 1100-88-63
S.E. X	M.E.	DAY X	NIGHT	

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Jolie, J.L.	1AC	1187902	PP	Nil	No. A.01	DATE 9-8
					D 14 (REVISED)	
					No. 1	CHECKED <input checked="" type="checkbox"/>
					#20	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
GA Major	7817/3690 Slight.	-	-	SOLO 3	DUAL 17	SOLO 3	DUAL 17

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

4
2
1
7
4
2
1
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
M X

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Sequences 11,12,13.

#1

TCA/PT
MA/17

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Taxied onto runway before making sure that no a/c was landing. When air line was noticed, the student taxied back off the runway too fast and struck a parked a/c with his wing tip.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~2 - Hitting other aircraft.~~

9

9. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

~~2. Carelessness.~~

ACTION TAKEN:

Log book endorsed. 7 days C.C.