

CASPIR Aircraft Accident Cards

Serial: V3312

Title: Airspeed Oxford Mk. I serial:V3312 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-17. Oxford II s/n V3312. This accident involved 1 person. Barber WF

Keywords: RAFOxford II,V3312,35 SFTS,35 Service Flying Training School,Aerodrome,1943-August-17,BarberRCAF L20

Created: 1943-08-17

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#V3312>

PURPOSE OF FLIGHT:

1) Flying training.

TECHNICAL OFFICER'S REPORT:

11

000/PSJ

NATURE OF ACCIDENT:

2) A/C hit obstruction on take-off
and burst tyre and ground looped
on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~11. Hit in obstruction.~~

12. Collision

13

SECONDARY OR CONTRIBUTORY FACTORS:

~~22. Pilot error~~

~~23. Tire failure~~

~~24. Ground loop~~

31. Tire Burst.

37

ACTION TAKEN:

Log book endorsed