

## CASPIR Aircraft Accident Cards

---

**Serial:** 1501

**Title:** Airspeed Oxford Mk. II serial:1501 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1943-August-27. They are: Oxford II s/n AS225, Oxford II s/n 1501. This accident involved 2 people. Clark FS, Denham JC

**Keywords:** RAFOxford II,1501,35 SFTS,35 Service Flying Training School,R1 Hamlin,1943-August-27,Clark,DenhamRCAF L20

**Created:** 1943-08-27

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#1501>

ACCIDENT CLASSIFICATION

UNIT 35 B.F.T.S. North Battleford 4		COM. 4	PLACE R1 Hamlin		DATE 27-8-43	TIME 1015	
A/C TYPE OXFORD II OXFORD II		NO. AS225 D 1501		CRASH CAT. "C"2 "C"5	H.Q. FILE 1300-AS225		S.E. M.E. DAY NIGHT X X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL
Denham, J.C.		LAC	1622756		Uninj.		No. DATE A11035 27-8
Clark, F.S.		LAC	1602583		Uninj.		D 14 (REVISED) No. CHECKED 8
							#28
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Cheetah X	178606/AS40687	Nil	INST.	NIGHT	ON TYPE		TOTAL
	178638/AS40719	Nil			SOLO	DUAL	SOLO DUAL
	179177/AS41258	Nil	9	5	6	12	39 45
	177950/AS40031	Nil	14	6	24	27	58 65

COMMAND

MONTH

STAGE OF FLIGHT

4  
2  
1  
7  
4  
2  
1  
1  
FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STAIRY  
FATAL  
INJURY  
3RD  
5  
RAF  
M 2

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Flying training.

TECHNICAL OFFICER'S REPORT:

Nil

100/1-0  
207/10

NATURE OF ACCIDENT:

A/C 1501 landed and turned across wind

A/C AS225 landed about fifty yds to left but swung to stbd hitting the nose of stationary a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~1. Swinging on landing.~~

2. Swung

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c.~~

ACTION TAKEN:

Nil