

ACCIDENT CLASSIFICATION

UNIT 35 B.F.T.S. North Battleford 4		COM. 4	PLACE R1 Hamlin		DATE 27-8-43	TIME 1015				
A/C TYPE OXFORD II OXFORD II		NO. AS225 D 1501		CRASH CAT. "C"2 "C"5	H.Q. FILE 1300-AS225		S.E.	M.E. X	DAY X	NIGHT
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Denham, J.C.			LAC	1622756		Uninj.		NO.	DATE	
Clark, F.S.			LAC	1602583		Uninj.		A11035	27-8	
								D 14 (REVISED)		
								NO. 8	CHECKED <input checked="" type="checkbox"/>	
								#28		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS						
Cheetah X		178606/AS40687 Nil		INST.	NIGHT	ON TYPE		TOTAL		
		178638/AS40719 Nil				SOLO	DUAL	SOLO	DUAL	
		179177/AS41258 Nil		9	5	6	12	39	45	
		177950/AS40031 Nil		14	6	24	27	58	65	

TYPE OF A/C
TYPE OF UNIT
CATEGORY
COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
5
RAJ
M X

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Flying training.

TECHNICAL OFFICER'S REPORT:

Nil

100/1-0
207/10

NATURE OF ACCIDENT:

A/C 1501 landed and turned across wind
A/C AS225 landed about fifty yds to left but swung to stbd hitting the nose of stationary a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~1. Swinging on landing.~~

2. Swung

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c.~~

ACTION TAKEN:

Nil