

CASPIR Aircraft Accident Cards

Serial: AJ736

Title: North American Harvard Mk. II serial:AJ736 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-07. Harvard II s/n AJ736. This accident involved 1 person. Gilje K

Keywords: RAFHarvard II,AJ736,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-07,GiljeRCAF L20

Created: 1943-09-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ736>

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 7-9-43	TIME 0115
A/C TYPE HARVARD II	NO. AJ736	CRASH CAT. "D"1	S.E. x	M.E.
		H.Q. FILE 1300-AJ736	DAY	NIGHT x

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Gilje, K.	LAC	2009	PP	Uninj.	NO. DATE

MONTH

D 14 (REVISED)	
NO. 11	CHECKED <input checked="" type="checkbox"/>
#60	

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Wasp S3H1	12176/262246 N11	INST.	NIGHT	ON TYPE		TOTAL	
		27	19	SOLO	DUAL	SOLO	DUAL
				56	80	101	126

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATIFY
FATAL
INJ.
3RD
INJURY
S

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Night flying cross country.

NATURE OF ACCIDENT:

Pupil damaged wing tip during night
Circuits and landings. A/m swung
during landing run through pupil
being unable to control it in
strong cross wind at night.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

35 Cross wind & gusts.

SECONDARY OR CONTRIBUTORY FACTORS:

61. Swinging on landing.

43. Tire trouble

ACTION TAKEN:

Nil