

## CASPIR Aircraft Accident Cards

---

**Serial:** FE826

**Title:** North American Harvard Mk. IIB serial:FE826 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-07. Harvard IIB s/n FE826. This accident involved 2 people. Johnstone LC, Ressiter A

**Keywords:** RAFHarvard IIB,FE826,34 SFTS,34 Service Flying Training School,Holsom R1,1943-September-07,Johnstone,RessiterRCAF L20

**Created:** 1943-09-07

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE826>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

"D" test practice.

Nil

NATURE OF ACCIDENT:

Port wing touched ground during landing run.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

35. Cross winds & gusts.

SECONDARY OR CONTRIBUTORY FACTORS:

32. Pilot error

ACTION TAKEN:

Log book endorsed "error Of judgment"