

62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 7-9-43	TIME 0225
A/C TYPE HARVARD IIB	NO. FE285	CRASH CAT. "D"1/72	H.O. FILE 1300-FE285	
			S.E. x	M.E.
			DAY	NIGHT x

CMDR

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Vojta, J.	LAC	787913	PP	Uninj.	

					NO.	DATE
					D 14 (REVISED)	
					NO. 13	CHECKED <input checked="" type="checkbox"/>
					#44	

MONTH

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS			
Wasp R1340AN1	21-12433/13910 Nil	INST.	NIGHT	ON TYPE	TOTAL
				SOLO	DUAL
		14	4	21	38
				SOLO	DUAL
				60	71

STAGE OF FLIGHT

TYPE OF A/C
TYPE OF UNIT
CATEGORY

7
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
5
4
RAF

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Night flying circuits and landings. Tail wheel tire burst after life of 213 hours 25 min.
NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil