

CASPIR Aircraft Accident Cards

Serial: 2575

Title: North American Harvard Mk.II serial:2575 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-08. Harvard II s/n 2575. This accident involved 2 people. Elliott RN, Ditmarsch E

Keywords: RAFHarvard II,2575,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-08,Ditmarsch,ElliottRCAF L20

Created: 1943-09-08

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2575>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Armanent exercise.

Tail wheel tire burst after life of 34.40 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst during landing run.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil