

## CASPIR Aircraft Accident Cards

---

**Serial:** 2793

**Title:** North American Harvard Mk.II serial:2793 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-12. Harvard II s/n 2793. This accident involved 2 people. Satten , Prosser DJ

**Keywords:** RAFHarvard II,2793,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-12,Prosser,SattenRCAF L20

**Created:** 1943-09-12

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2793>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Familiarization  
NATURE OF ACCIDENT:

Tail wheel tire burst after life of 11.55 hours.

Tail wheel tire burst while taxiing

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil