

CASPIR Aircraft Accident Cards

Serial: FE829

Title: North American Harvard Mk. IIB serial:FE829 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-14. Harvard IIB s/n FE829. This accident involved 2 people. Chippindall G, Mason IO

Keywords: RAFHarvard IIB,FE829,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-14,Chippindall,MasonRCAF L20

Created: 1943-09-14

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE829>

ACCIDENT CLASSIFICATION

UNIT **34 S.F.T.S. Medicine Hat** COM. **4** PLACE **M.A.** DATE **14-9-43** TIME **1700**
 H.Q. FILE **1300-FE829**

A/C TYPE **HARVARD IIB** No. **FE829** CRASH CAT. **"D"_{1/2}** S.E. **x** M.E. DAY **x** NIGHT

| PERSONNEL | RANK | NUMBER | DUTY | INJURIES | SIGNAL | |
|-----------------|------|--------|------|----------|----------------|---------|
| Chippindall, G. | SGT | 654506 | FI | Uninj. | No. | DATE |
| Mason, I.O. | F/S | 635725 | PP | Uninj. | D 14 (REVISED) | |
| <i>Incident</i> | | | | | No. | CHECKED |
| | | | | | 32 | ✓ |
| | | | | | #85 | |

| ENGINE | ENGINE NUMBER (S) | HOURS FLOWN BY PILOTS | | | | | |
|------------------------|-------------------|-----------------------|-------|---------|------|-------|------|
| | | INST. | NIGHT | ON TYPE | | TOTAL | |
| | | | | SOLO | DUAL | SOLO | DUAL |
| Wasp III R1340-AN-1 | 42-1149/21073 Nil | - | - | 68 | 92 | 201 | 149 |
| | | - | - | 1 | 3 | 14 | 40 |

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
INJURY

TYPE OF A/C
TYPE OF UNIT
CATEGORY

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

PURPOSE OF FLIGHT:

Essential dual

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

A/C landed with drift and swing,
causing damage to wing tip.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

61. Swinging on landing.

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Nil