

CASPIR Aircraft Accident Cards

Serial: AJ919

Title: North American Harvard Mk. II / 2 serial:AJ919 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-16. Harvard II s/n AJ919. This accident involved 1 person. Wright RTJ

Keywords: RAFHarvard II,AJ919,41 SFTS,41 Service Flying Training School,Aerodrome,1943-September-16,WrightRCAF L20

Created: 1943-09-16

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ919>

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. WEYBURN	COM. 2	PLACE M.A.		DATE 16-9-43	TIME 1300			
	A/C TYPE HARVARD II	No. AJ919	CRASH CAT. "C"2	H.Q. FILE 1300-AJ919				
PERSONNEL Wright, R.T.J.		RANK F/O	NUMBER 50853	DUTY PP	INJURIES Uninj.			
				SIGNAL				
				No. A.166	DATE 16-9			
				D 14 (REVISED)				
				No. 6	CHECKED <input checked="" type="checkbox"/>			
				#82				
ENGINE Wasp S3HL	ENGINE NUMBER (S) 9040/4599 Nil		HOURS FLOWN BY PILOTS					
			INST.	NIGHT	ON TYPE	TOTAL		
					SOLO	DUAL	SOLO	DUAL
			13	5	8	19	44	53

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3RD
RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Exercises. 13,15,17.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pilot was making landing with strong, gusty, cross wind when a/c ground looped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

15/1/55/1000

CLASSIFICATION:

~~38. Ground loop.~~

2. Swing 2

SECONDARY OR CONTRIBUTORY FACTORS:

~~35. Cross winds and gusts.~~

ACTION TAKEN:

Nil