

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S.  
Medicine Hat

COM. 4

PLACE Holsom, RI

DATE 20-9-43 TIME 1625

H.Q. FILE 1300-FE825

A/C TYPE HARVARD IIB

No. FE825

CRASH CAT. "D"<sup>4</sup>/<sub>4</sub>

S.E. X

M.E.

DAY X

NIGHT

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Jiraneck, J.

CPL 787321

PP

Uninj.

No.

DATE

D 14 (REVISED)

No.

CHECKED

45

MONTH

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJ.

3RD

INJURY

RAF

STAGE OF FLIGHT

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Wasp  
R1340-AM-1

42-1145/21069 Nil

INST.

NIGHT

ON TYPE

TOTAL

-

-

1

SOLO

10

SOLO

40

DUAL

57

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Nil

Local solo exercises.

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Pupil landed on the runway in a cross wind. A swing commenced, which he failed to correct in time to prevent a wing tip striking the ground.

CLASSIFICATION:

35. Cross winds and gusts.

SECONDARY OR CONTRIBUTORY FACTORS:

61. Swinging on landing.

32. Pilot error.

ACTION TAKEN:

Log book endorsed.