

PURPOSE OF FLIGHT:

Test for night flying.

NATURE OF ACCIDENT:

Stbd motor caught fire after take-off
Made forced landing as he was unable
to maintain height on one engine.

TECHNICAL OFFICER'S REPORT:

Cause of fire obscure due to extent of
damage to engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

O/M/T/O/P/E/F/N/A/S/N-10/AE

CLASSIFICATION:

~~27. Fire in the air.~~

15 Forced Land

5

SECONDARY OR CONTRIBUTORY FACTORS:

28. Fire - In Air.

28

ACTION TAKEN:

Nil