

CASPIR Aircraft Accident Cards

Serial: FP763

Title: Avro Anson Mk. II serial:FP763 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-September-17. Anson II s/n FP763. This accident involved 4 people. Carter AW, McLeod ANS, Ross JA, Ruhen OH

Keywords: RCAFAnson II,FP763,7 BGS,7 Bomb & Gunnery School,Aerodrome,1943-September-17,Carter,McLeod,Ross,RuhenRCAF L20

Created: 1943-09-17

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP763>


ACCIDENT CLASSIFICATION

UNIT 7 B.G.S. Paulson		COM. 2	PLACE M.A.			DATE 17-9-43	TIME 0900			
A/C TYPE ANSON II		NO. FP763		CRASH CAT. Nil		S.E.	M.E. x	DAY x	NIGHT	
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Ruham, O.H.			NZ	F/S 417116	P	Uninj.		No.	DATE	
McLeod, A.N.S.			LAC	R189453	AB	Uninj.		D 14 (REVISED)		
Ross, J.A.			LAC	R191981	AB	Uninj.		No.	CHECKED	
Carter, A.W.			CPL	R172151	BI	Uninj.		1	<input checked="" type="checkbox"/>	
								#24		
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS					
Jacobs		2524/9794 Nil			INST.	NIGHT	ON TYPE		TOTAL	
		25411/9781 Seriously					SOLO	DUAL	SOLO	DUAL
					29	128	278	1	526	121

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKEOFF
FLIGHT
STAIRY
FATAL
INJURY
3RD
M X



PURPOSE OF FLIGHT:

Bombing exercise.

NATURE OF ACCIDENT:

Pilot observed oil spray from Port
motor. Noted oil pressure 0. Engine
failed before pilot could switch off.
Pilot landed a/c on aerodrome.

TECHNICAL OFFICER'S REPORT:

Lack of oil due to rocker box scavenge line elbow
being fractured.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

SEE/EN/OM/MP

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil