



PURPOSE OF FLIGHT:

- (1) Seq. 25 (6,7,8)
- (2) Seq. 25 (6,7,8)

TECHNICAL OFFICER'S REPORT:

No technical failure. *M. H.*

NATURE OF ACCIDENT:

Anson 8418 taxied into Anson 8330 parked at taxiing post. Pupil pilot negligently allowed A/C to move forward while doing pre-take off check.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

9. Collisions *9*

SECONDARY OR CONTRIBUTORY FACTORS:

~~21. Carelessness.~~

ACTION TAKEN:

Log Book endorsed "Carelessness."

7 days detention.